

# 137 | PN 10

Indicatore di livello in ottone a passaggio libero |  
*Brass level gauge, free way type*

| codice   code | 137A01   | 137A02   | 137A03   | 137A04   | 137A05  | 137A06      |
|---------------|----------|----------|----------|----------|---------|-------------|
| misura   size | 1/4 x 10 | 3/8 x 13 | 1/2 x 16 | 3/4 x 18 | 1" x 25 | 1" 1/4 x 30 |

